	•	

## (SUBMIT IN TRIPLICATE)

## UNITED STATES **DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY**

	Budget Bureau No. 42-R358.4. Approval expires 12-31-60.
Land Of Lease No	HIS-04106
Unit	

## SUNDRY NOTICES AND REPORTS ON WELLS

<b>3.</b>
REPAIR
G
F
N R

SEL Section 3 (1/2 Sec. and Sec. No.) (Meridian) (Twp.) (Range) (County or Subdivision)

(State or Territory)

The elevation of the derrick floor above sea level is ft.

## **DETAILS OF WORK**

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

To 1025'. Hele full of heavy and. Sat a 50' play (10 sacks coment) at surface. Plumped and chandened 3-2-40. Mather exceted 3-3-40.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Courty Last Courty	
Address 204 Rosbert Indiadang	11/1/
Albuquerque, Nor Moules By	John Jiki-
Title _	John Liki-