NEW MEXICO OIL CONSERVATION COMMISSION MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY <u>Repair Cil & Refining Company</u> (Add	ress)	Parmington,	New Mexico	<u> </u>
Jicarilla Apache	A HATTO	5 C 4	m 48	7 D ##
LEASE Tribe "J" WELL NO.				
DATE WORK PERFORMED 12, 195	POOL	South Blan	neo Picture	d Cliffs
This is a Report of: (Check appropriate l	olock)	Results o	of Test of (Casing Shut-off
Beginning Drilling Operations		Remedia	l Work	
Plugging		Other_		
Detailed account of work done, nature and	l quantity of	materials	used and a	results obtaine
Ran and set Baker Model K bridge plug at 2 100 sacks of neat cement. Broke formation Pulled 2800° of 2" tubing out of hole. Removed wellhead. Placed 10 sack of cement Left 307° of 8-5/8" easing and 2918° of 5-2	with 4000f,	broke to 3	600#. /2*).	2826-2676 with
Well identification markers installed in a commission regulations.	ceordance wi	th New Mexi	eo Oil con	ervation
fell plugged and abandoned.				
FILL IN BELOW FOR REMEDIAL WORK Original Well Data: DF Elev. TD PBD	· •		Compl D	ate
Thng. Dia Thng Depth C			 Oil String :	
Perf Interval (s)			J	*
	ing Formati	ion (s)		
RESULTS OF WORKOVER:	· · · · · · · · · · · · · · · · · · ·	BEFC	DRE	AFTER
Date of Test				
Oil Production, bbls. per day				
Gas Production, Mcf per day				
Water Production, bbls. per day				
Gas-Oil Ratio, cu. ft. per bbl.				
Gas Well Potential, Mcf per day				
Witnessed by				
			(Compan	y)
OIL CONSERVATION COMMISSION	I hereby certify that the information given above is true and complete to the best of			
Name Original Signed Emery C. Arnold	my knowil		P 10 Dua	sell M. Lilly
Title Supervisor Dist. # 3	Name Position	<i>Melly III. I</i> Matrict Sur		
Date 3 8 1957	,	Hymble Oil		



OIL CONSERVATION COMMISSION AZTEC DISTRICT OFFICE				
No. Copies Rec	eived 3			
DISTRIBUTION				
	FURLISHED	·		
rator				
Santa for				
Coration Office	The state of the s			
Try o Late 4 Company				
2.5. G 3		~ ~~		
Transporte:				
File	7			