

## (SUBMIT IN TRIPLICATE)

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office	Santa Fe
Lease No	078885
Unit Ce	myon Largo

NOTICE OF INTENTION TO	DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF. X
NOTICE OF INTENTION TO	CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.
	TEST WATER SHUT-OFF	ALIENMO CASMO
	RE-DRILL OR REPAIR WELL	The state of the s
	SHOOT OR ACIDIZE	
	ABANDON WELL	
	(INDICATE ABOVE BY CHECK MA	RK NATURE OF REPORT, NOTICE, OR OTHER DATA)
HOME-GOVERNME	NT #1-1:	July 16, 19_56
/ell No. <b>1-1</b>	is located 1120 ft. fro	m. $\begin{bmatrix} E \\ S \end{bmatrix}$ line and 1145 ft. from $\begin{bmatrix} E \\ M \end{bmatrix}$ line of sec. 1
SE/4 Section (% S)2. and Sec. No.	25% (Twp.)	(Range) (Meridian)
-Wildest	- Rio Arrib	y or Subdivision)  New Mexico (State or Territory)
		The state of the s
he elevation of the	) derrick floor above sea l	level is <b>6730.</b> At.
		AILS OF WORK
tate names of and expected	•	wiles OF WORK sizes, weights, and lengths of proposed casings; indicate inudding jobs, cement-
tare names of and expected	ing points, and al	l other important proposed work)
TOP PICTURED	CLIFFS 2865 (/3865)	<u>)</u>
MOMAT PORTERS	AGEC DISTRICT ACCIDE	
TOTAL DEPTH:	2955 PETD: 2904	
		2955
Ran 5-1/2", 1	4.0#, J55, R-2, STM	C casing to 2865', comented w/125 sax Regular
cement. FP 120	00#. Job complete @	12:15 PM, 7-9-56. Landed casing, released
Partorsted 4 /	u in Caole 1001s (+. hullets 2867-2868	14-56, swabbed and cleaned out to 2904, Set 1-1/2 hrs, ran bailer, no entry.
101101000	222000	bet anale mind the success in entry
CASING TEST O	<u>.X.</u>	
I understand that this pl	an of work must receive approval	in writing by the Geological Survey before operations may be commenced.
ompany	The Superior Uil	Company
	Midland, Texas	
	······································	
		Bylling Mollus (An. J. Mathis

U. S. GOVERNMENT PRINTING OFFICE 16-8437-6