Form 9-331 a (Feb. 1951)

X

Farmington, New Mexico

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. SF 080473
Unit Jillson

DEGELAED

			님	U E "	
SUNDRY	NOTICES A	AND REPOR'	TS ON WELL	S (EC 1: 1960	
NAMES OF INTENTION TO DOUG		SURSFOLIENT REPOR	RT OF WATER SHUT-OFF	, = 0	
NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPOR		REOLOGICAL SUR	
IOTICE OF INTENTION TO TEST WAT	t t	SUBSEQUENT REPOR	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING EOLOGICAL SUR SUBSEQUENT REPORT OF ALTERING CASING TO THE TOTAL SUR		
OTICE OF INTENTION TO RE-DRILL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR			
IOTICE OF INTENTION TO SHOOT OF					
NOTICE OF INTENTION TO PULL OR					
OTICE OF INTENTION TO ABANDON	i				
(INDICA	TE ABOVE BY CHECK MAR	K NATURE OF REPORT, NOTI	CE, OF: OTHER DATA)		
		Decembe	r 14	, 19 <u>60</u> _	
ell No. 1 is loca	ted990 ft. fron	$\mathbf{n}_{-}\left\{ egin{array}{c} \mathbf{N} \\ \mathbf{S} \end{array} ight\}$ line and -79	0 ft. from $\left \begin{array}{c} \mathbf{W} \\ \mathbf{W} \end{array} \right $ line	of sec. 4	
₩ ‡ Sec. 4		()	· · ·	OF!	
(1/4 Sec. and Sec. No.)			(Meridian)	THAT Y	
avilan P C Ext	Rio Arri	or Subdivision)	(State T Telt		
ne elevation of the derrick		ILS OF WORK			
ate names of and expected depths t	o objective sands; show si ing points, and all	izes, weights, and lengths o other important proposed	f proposed casings; indicate m work)	audding jolss, cement	
Spud 11-30-60			·	**************************************	
Cemented 8 5/8 casing ressure tested casing 5' off be ressure tested casing cas	ng to 600 psi. ottom at 3845; ng to 1500 psi. Pictured Cliff	Held 0 K for 30 with 150 sacks. Held pressure 2s 3807-3825 wit	o minutes. Cemento for 30 minuts. No th 72 holes. Frac	ed o treated	
I understand that this plan of wo	k must receive approval i	n writing by the Geologica	l Survey before operations ma	y be commenced.	
ompany John A. Ega	<u>a</u>				
ddress Box 208					

GPO 918507

By Jim & Cyan

Title Operator