

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☒ gas well ☐ other ☐

2. NAME OF OPERATOR

Southern Union Exploration Company of Texas

3. ADDRESS OF OPERATOR

1217 Main Street, Dallas, Texas 75202

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 1980' FS & EL, Sec. 36

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH: T24N, R1W, 3845-4123

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐CHANGE ZONES ☐ABANDON* ☐

(other) Change of operator's name and address.

SUBSEQUENT REPORT ☐RECEIVED
MAR 02 1981(NOTE: Report results of multiple completions change on Form 9-330.)
U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Change of operator's name and address, effective 12/30/80 from:

Southern Union Exploration Company
1217 Main Street
Dallas, Texas 75202

Subsurface Safety Valve: Manu. and Type _____

18. I hereby certify that the foregoing is true and correct

SIGNED Ronald M. Lantz TITLE Drilling & Production Engineer DATE 2/27/81

(This space for Federal or State office use)

APPROVED BY _____

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

DEC 2 1981

*See Instructions on Reverse Side

BY [Signature] FARMINGTON DISTRICT

NMOCC