

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1494.

5. LEASE DESIGNATION AND SERIAL NO.

Jicarilla 363

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Jicarilla Apache

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Jicarilla 363

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Undesignated

11. SEC., T., R., M., OR B.L.K. AND SURVEY OR AREA

Sec. 21, T-24-N, R-4-W

N.M.P.M

12. COUNTY OR PARISH

Rio Arriba

13. STATE

N.M.

14. PERMIT NO.

15. ELEVATIONS (Show whether DP, RT, GR, etc.)

8859' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and names pertinent to this work.)*

4-6-73 Drilling at 3250'. Rig down 7 hours - mechanical failure
Md. wt. 8.8 lbs Vis. 29 WL 8.5 cc

4-7-73 Drilling at 3667' - No significant shows in Chacra Mud wt. 8.8#
Vis. 29, WL 8.4

4-8-73 Drilling at 4050' - 20' per hr. Mud 9.0# Vis. 33 WL 11

18. I hereby certify that the foregoing is true and correct

SIGNED

Raymond M. Casey

TITLE

President

DATE 4-9-73

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

APR 10 1973

*See Instructions on Reverse Side

COPY TO ROSWELL