					/
Form 9-331 (May 1963)	DEPAR'		INTERIOR	SUBMIT IN TRIPLICATE (Other instructions on r verse side)	Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.
GEOLOGICAL SURVEY					Contract 35
SIII	ADBA MC	TICES AND REP	ORTS ON	WELLS	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  Use "APPLICATION FOR PERMIT—" for such proposals.)					Jicarilla Apache
1. OIL CT GAS					7. UNIT AGREEMENT NAME
WELL X WELL OTHER					8. FARM OR LEASE NAME
2. NAME OF OPERATOR					
Clinton Oil Company 3. ADDRESS OF OPERATOR					Jicarilla 35
					2
P. O. Box 2434, Casper, Wyoming 82601  4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*					10. FIELD AND POOL, OR WILDCAT
See also space 17 b	elow.)	Otero Gallup			
III Bullace		11. SEC., T., B., M., OR BLK. AND			
					SURVEY OR AREA
990' FSL, 990' FWL, Sec. 36, T25N, R5W					36, T25N - R5W
14. PERMIT NO.	PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6798' GLM, 6809' RBM				12. COUNTY OR PARISH 13. STATE
					Rio Arriba N. Mex.
16.	Chack	Appropriate Box To	Indicate Natu	re of Notice. Report, or	Other Data
16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:					
	NOTICE OF IN			[	
TEST WATER SHUT	-OFF	PULL OR ALTER CASING		WATER SHUT-OFF	REPAIRING WELL ALTERING CASING
FRACTURE TREAT		MULTIPLE COMPLETE		FRACTURE TREATMENT SHOOTING OR ACIDIZING	ABANDONMENT*
SHOOT OR ACIDIZE		ABANDON* CHANGE PLANS			cement prod.csg. X
REPAIR WELL	L	lts of multiple completion on Well appletion Report and Log form.)			
(Other)	OR COMPLETED	OPERATIONS (Clearly state	all pertinent de	tails and give nertinent dat	es, including estimated date of starting any
proposed work. nent to this work	If well is dire	ectionally drilled, give sur	suriace locations	and measured and true ver	ical depens for the maracis and south perm
8-5-74 DST	#1 Mene	fee Sand - test	interval 4	4 <b>7</b> 94' - 4859' RB	MI.
IF 14 min -	fair blov	v - no gas to su	irface - 1	06 PSI	
ISI 46 min.	- 1635 P	SI			
FF 60 min.	- strong	blow w/gas to	surface i	n <mark>20 min</mark> decr	eased - unable to
gauge in 5 min 185 PSI					
FSI 90 min.					
			:8.WCM -	120' G&DIST cut	water
1,000 11	ura boc	J G C WI 120 G	100 W C 111	140 Gabibi cat	William C.
Cemented in cement tails 1st plug dov	n 2 stage ed in with vn at 12:3	s with DV colla n 100 sks Class	ar at 4961 s ''B''. 2n at 6551' -	' RBM。1st stag d stage 208 sks ' - 2nd plug down a	nd set at 6582' RBM. e 200 sks 'lite weight' lite weight' cement. t 5:30 AM 8-11-74
			والمعطيفين الدعورة وعار	er en	and the second s
		,			(67 1 7 1874
18. I hereby certify the	at the favorati	ng is true and correct	Contraction of the second	84.	
16. I hereby certary th	10 10 1	Sale and correct	L. S P	Forugion Engine	er DATE October 15, 19

DATE \_\_

TITLE \_

(This space for Federal or State office use)

APPROVED BY CONDITIONS OF APPROVAL, IF ANY: