## UNITED STATES

5. LEASE		
SF 078911	•	

GEOLOGICAL SURVEY	SF_078911
	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME Lindrith Unit 8. FARM OR LEASE NAME
1. oil gas well other	Lindrith Unit -  9. WELL NO.
2. NAME OF OPERATOR	98
EL PASO NATURAL GAS COMPANY  3. ADDRESS OF OPERATOR	So. Blanco PC
Box 289, Farmington, New Mexico 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)	11. SEC., T., R., M., OR BLK. AND SURVEY OF AREA Sec. 3, T-24-N, R-3-W N.M.P.M.
AT SURFACE: 1165'S,1450'W AT TOP PROD. INTERVAL:	12. COUNTY OR PARISH Rio Arriba New Mexico
AT TOTAL DEPTH:	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	<b> </b>
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD 7046' G.L.
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	7070 3.2.
TEST WATER SHUT-OFF   X   FRACTURE TREAT	(NOTE: Report results of multiple completion or zon- change on Form 9–330.)
(other)	
<ul> <li>17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statincluding estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertine</li> <li>-79: Spudded well. Drilled surface hole. Ran 3 casing 133' set at 145'. Cemented w/182 cu.</li> </ul>	directionally drilled, give subsurface locations and ent to this work.)*  joints 8 5/8", 24#, KE surface

AUG 71979 OIL CON. COM. DIST. 3

Red (

Subsurface-Safety Valve: Manu. and Type			Set @E		
18. I hereby certify that the forest	oing is true and correct  Mill TITLE Drilling Clerk	DATE	August	1, 1979	
	(This space for Federal or State office u	se)			
APPROVED BY	TITLE	DATE		· · · · · · · · · · · · · · · · · · ·	

AUG 6 1979