

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other ☐
well well

2. NAME OF OPERATOR
Grace Petroleum Corporation

3. ADDRESS OF OPERATOR
3 Park Central, 1515 Arapahoe, Denver, CO 80202

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 960' FSL, 960 FWL'

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON* ☐

(other) ☐

Report on rig activities

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

5/14/80 Report resumed from 5/3/80. Drl. cmt strgs fr 3090-3103'.

5/25/80 Tst csg to 3500 psi.

5/29/80 Perf, sqz hole at 5585'. Press csg to 600 #, press tbq to 1400 #.
Unable to pmp into frm.

5/30/80 Perf 5664-5672'. Swab

5/31/80 Swab run, fl 5100'. Acd

6/1/80 TPO. Swab. Frac.

6/4/80 Swab 3 bbls highly frac cut fl, 80% wrt, 20% oil.

RECEIVED
AUG 3 1980
U.S. GEOLOGICAL SURVEY
FARMINGTON, N. M.

Subsurface Safety Valve: Manu. and Type

Set @

Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

DATE

July 31, 1980

(This space for Federal or State office use)

ACCEPTED FOR RECORD

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

AUG 12 1980

FARMINGTON DISTRICT

BY

*See Instructions on Reverse Side

NMCCG