Form	9–331
Dec.	1973

_			
1	Εi	ı	ρ

Form 9-331 6 BLM 1 Southern Union	Form Approved. Budget Bureau No. 42–R1424
UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	NM 25425
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
	Grand Gulch
1. oil gas other P & A 2. NAME OF OPERATOR	9. WELL NO.
DUGAN PRODUCTION CORP.	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Hildcat PC, Ballard
P O Box 208, Farmington, NM 87499	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	Sec. 6, T24N, R7W, NMPM
below.) AT SURFACE: 1120' FSL - 880' FWL	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL:	Rio Arriba NM
AT TOTAL DEPTH:	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 7085 GL
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	7000 42
TEST WATER SHUT-OFF	
FRACTURE TREAT SHOOT OR ACIDIZE	
REPAIR WELL	NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING	, , , , , , , , , , , , , , , , , , ,
CHANGE ZONES	1.41984
ABANDON* BUREAU OF LA	4D fearthagulatery (
(other)	The state of the s
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is demanded and true vertical depths for all markers and zones pertinent	lifectionally diffied, give autourace locations and
The Grand Gulch #1 was plugged and abandone	ed on 9-11-84 as follows:
1. Squeezed 5 sks cement into perfs 2484'	- 2494'.
2 Spotted 22 sks cement plug from 2484 to) 1930, (100, apole rob of old viguo).
2 Spotted 8 sks cement blug from 290' to	surtace.
4. Installed dry hole marker and cleaned a	and restored rocation.
The surface rehabilitation requirements neo have been accomplished as required by BLM 1	cessary for permanent abandonment letter dated 9-15-83.
The location is now ready for BLM inspection	on.
Subsurface Safety Valve: Manu. and Type	Set @ Ft.
18. I hereby certify that the foregoing is true and correct	
SIGNED Sharper Burger Geologist	9-12-84 DPROVED
(This space for Federal or State by	
APPROVED BY TITLE	
CONDITIONS OF APPROVAL, IF ANY:	DEC 1 3 1984 DEC 1 0 1984
	OII CORE DEC MCKAR

Liability under bond is retained until surface restoration is completed.

MOCE actions on Reverse Side

DIST. 3

15/ J. Star McKee MILLENBACH AREA MANAGER