Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. Lease Designation and Serial No. SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Jicarilla Contract 146 ROUE. N.A Use "APPLICATION FOR PERMIT - " for such proposals age ALBUQU Jicarilla Apache 7. If Unit or CA, Agreement Designation 1. Type of Well Oil Well X Gas 8. Well Name and No. Other Jicarilla Contract 146 36 2. Name of Operator Attention 9. API Well No. Amoco Production Company Patty Haefele 3. Address and Telephone No. 3003922486 (303) 830-4988 10. Field and Pool, or Exploratory Area P.O. Box 800, Denver, CO Otero Chacra/Blanco Mesaverde 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. County or Parish, State T 25N R 5W Unit A 840' FNL 1030' FEL Rio Arriba **New Mexico** CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF ACTION TYPE OF SUBMISSION Notice of Intent Water Shut-Off Bradenhead, DHC inal Abandonment Notice (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work . If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.]*

Amoco Production Company has performed the following work:

MIRUSU 3/29/96. Set RBP 2500'. Cap with 10' of sand.. Pressure test casing to 1000 psi, held ok. Run CBL 100-2193'. TOC 813'. Perforated at 800' with 2 shots. Cemented 13-800' with 260' Class B cement, 15.6 ppg. Dispace with 12 bbls when cement locked up, took pressure to 1500 psi and left top of cement at 452'. Drill out 452-848'. Pressure test casing to 500 psi, failed. Spotted 25 sx Class B cement at 863'. Squeezed down casing 1500 psi, displaced 1/2 bbl into formation. Drill out 649-868'. Pressure test casing 500 psi, ok. Circulate sand off RBP, swabbed water out of casing and pulled out of hole. Mill out packer 4050-4055', circulate clean. Cleanout 5285-5311'. Kicked off well. Swab and flow well. RDMOSU 4/11/96.

MAY 1 0 1996

14. I hereby certify that the foregoing is true and correct
Signed Patry Haefele

Title Staff Assistant
Date

OH. GOV. DIV.

OH. GOV. DIV.

OH. GOV. DIV.

Title Staff Assistant
Date

OH-18-1996

Title Chief, Lands and Mineral Resources
MAY 9 1996

Title Date