## CANYON LARGO UNIT 311 Section 3, T24N, R6W Rio Arriba County, New Mexico

## SLOPE TESTS

Depth	Hole Deviation		
212	1/2°		
1599	1-3/4°		
2651	1 °		
4828	1 °		
5675	1 °		



State	of :	New 1	Mexico	)	
				)	ss
County	of	San	Juan	)	

I, Steven S. Dunn I, Steven S. Dunn, being first duly sworn, depose and state that the above and foregoing depth and hole deviation figures are true and correct to the best of my information and belief.

Subscribed and sworn before me this

day of 1982

My Commission Expires Dec. 11, 1985