UNITED STATES

5. LEASE	
NM - 42417	

DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	NM - 4241/ 6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME	
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME	
1. oil gas X other	Capulin Mesa	
well well other	9. WELL NO.	
2. NAME OF OPERATOR	2	
Southland Royalty Company	10. FIELD OR WILDCAT NAME	
3. ADDRESS OF OPERATOR	Gavilan Pictured Cliffs	
P.O. Drawer 570, Farmington, NM 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA	
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)	Section 31, T25N, R1W	
AT SURFACE: 800' FSL & 1650' FWL	12. COUNTY OR PARISH 13. STATE	
AT TOP PROD. INTERVAL:	Rio Arriba New Mexico	
AT TOTAL DEPTH:	14. API NO.	
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,		
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)	
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	7414' GL	
TEST WATER SHUT-OFF	(NOTE: Report results of multiple completion of zone change on Ferm 9-330)	
 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dimeasured and true vertical depths for all markers and zones pertinen 9-7-82 Spudded 12-1/4" surface hole at 1:45 pm 235'. Set 5 joints (214.80') of 8-5/8" with 177 cubic feet of Class "B", 1/4# 10:45 pm on 9-7-82. Cement circulated 	rectionally drilled, give subsurface locations and to this work.)* on 9-7-82 and drilled to a TD of , 40#, casing at 227'. Cemented gel flake, 3% CaCL2. Plug down at	
Subsurface Safety Valve: Manu. and Type 18. I hereby pertify that the foregoing is true and correct SIGNED SIGNED TITLE Secretary (This space for Federal or State office)		
(This space for Federal or State offi	ce use)	
APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY:	LOCEPTES FOR RECORD	

SEP 10 1982