

submitted in lieu of Form 3160-5

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

1. Type of Well

GAS

2. Name of Operator

**BURLINGTON  
RESOURCES**

OIL & GAS COMPANY

3. Address & Phone No. of Operator

PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M

800' FSL, 1650' FWL, Sec. 31, T-25-N, R-1-W, NMPM

N

5. Lease Number  
NM-42417

6. If Indian, All. or  
Tribe Name

7. Unit Agreement Name

8. Well Name & Number  
Capulin Mesa #2

9. API Well No.  
30-039-23049

10. Field and Pool  
Gavilan Pict. Cliffs

11. County and State  
Rio Arriba Co, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

Type of Action

<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Abandonment	<input type="checkbox"/> Change of Plans
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion	<input type="checkbox"/> New Construction
<input type="checkbox"/> Final Abandonment	<input type="checkbox"/> Plugging Back	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> Water Shut off
	<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Conversion to Injection
	<input checked="" type="checkbox"/> Other - Casing integrity test	

13. Describe Proposed or Completed Operations

Please find attached the casing integrity test for the subject well. A 30 minute test was conducted 10-25-96. Pressure at beginning of the test was 500 psi. Pressure at the end of the was 220 psi.

RECEIVED  
JAN 10 1997

OIL CON. DIV.  
DIST. 3

14. I hereby certify that the foregoing is true and correct.

Signed [Signature] Title Regulatory Administrator Date 12/12/96

(This space for Federal or State Office use) Chief, Lands and Mineral Resources  
APPROVED BY [Signature] Title Chief, Lands and Mineral Resources Date JAN 9 1997

CONDITION OF APPROVAL, if any:

Submit Sundry outlinig plan for repair of the well casing.

