

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(See instructions on the reverse side of this form for details on how to complete this form. Use separate forms for each well.)

- 1. Well Other
- 2. NAME OF OPERATOR
Arco Production Company
- 3. ADDRESS OF OPERATOR
501 Airport Drive, Farmington, NM 87401
- 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 790' ENL x 1580' FEL.
AT TOP PROD. INTERVAL: Same
AT TOTAL DEPTH: Same
- 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

- | | |
|---|--------------------------|
| REQUEST FOR APPROVAL TO: | SUBSEQUENT REPORT OF: |
| TEST WATER SHUT-OFF <input type="checkbox"/> | <input type="checkbox"/> |
| FRACTURE TREAT <input type="checkbox"/> | <input type="checkbox"/> |
| SHOOT OR ACIDIZE <input type="checkbox"/> | <input type="checkbox"/> |
| REPAIR WELL <input type="checkbox"/> | <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | <input type="checkbox"/> |
| MULTIPLE COMPLETE <input type="checkbox"/> | <input type="checkbox"/> |
| CHANGE ZONES <input type="checkbox"/> | <input type="checkbox"/> |
| ABANDON* <input type="checkbox"/> | <input type="checkbox"/> |
| (other) cement top <input type="checkbox"/> | <input type="checkbox"/> |

5. UIC#
Jicarilla Contract 146

6. INDIAN, ALLOTTEE OR TRIBE NAME
Jicarilla Apache

7. UNIT AGREEMENT NAME

8. FANG RELEASE NAME
Jicarilla Contract 146

9. WELL NO.
13E

10. FIELD OR WILDCAT NAME
Gonzales Mesaverde/Basin Dakota

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA NW/NE, Section 9, T25N, R5W

12. COUNTY OR PARISH. 13. STATE
Rio Arriba New Mexico

14. API NO.
30-039-23165

15. ELEVATIONS (SHOW DF, KDB, AND WD)
6704' GL

(NOTE: Report results of multiple completion or zone change on Form 9-330)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

In response to your notice of July 29, 1983, when the 7" casing was cemented, 12 bbls of cement were circulated to surface.

[Handwritten signatures and stamps]
OIL COMPANY

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct
SIGNED D.D. Lawson TITLE Dist. Admin. Supvr DATE 8/9/83

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: _____

ACCEPTED FOR RECORD

AUG 19 1983

*See Instructions on Reverse Side

NMOCC

FARMINGTON RESOURCE AREA
FARMINGTON, NEW MEXICO
BY Smm