7.mc 3160−5 iovember 1983) Formerly 9-331)

16.

UNITED STATES DEPARTMENT OF THE INTERIOR VERNE BLIDE

| SUBMIT | | | | |
|------------|---|---------|----|----|
| (Other 1 | | uctions | on | re |
| waren elde | 1 | | | |

Budget Bureau No. 1004-0135 Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

Jicarilla Contract 147 6. IF INDIAN, ALLOTTEE OR TRIBE NAME

| | SUNDRY NOTICES AND REPORTS ON WELLS | |
|---------|--|----|
| (Do not | use this form for proposals to drill or to deepen or plug back to a different reservoi Use "APPLICATION FOR PERMIT-" for such proposals.) | r, |

BUREAU OF LAND MANAGEMENT

Jicarilla Apache

| OIL X CAB X OTHER | UNIT AGREEMENT NAME |
|--|--|
| 2. NAME OF OPERATOR | 8. FARM OR LEASE NAME |
| Amoco Production Company | Jicarilla Contract 147 |
| 3. ADDRESS OF OPERATOR | 9. WELL NO. |
| 501 Airport Drive, Farmington, New Mexico 87401 | 9E |
| See also space 17 below.) | 10. FIELD AND POOL, OR WILDCAT |
| 44 - 11 - 12 - 13 - 13 - 13 - 13 - 13 - 13 | Gallup√Basin Dakota |
| 910' FSL x 1740' FEL JAN 18 18 18 18 18 18 18 18 18 18 18 18 18 | 11. SHC., T' E., M., OR BLK. AND SURVEY OR AREA |
| OF LANGOUS | |

15. ELEVATIONS (Show whether BEAT OF ON SW/SE, Section 7, T25N, R5W 14. PERMIT NO. 6664' GL Rio Arriba New Mexico

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

| NOTICE OF INTENTION TO: | | | SUBSEQUENT REPORT OF: | | | | |
|-------------------------|--|----------------------|-----------------------|-----------------------|------------------|---------------------------------------|---|
| TEST WATER SHUT-OFF | | PULL OR ALTER CASING | | WATER SHUT-OFF | | REPAIRING WELL | |
| FRACTURE TREAT | | MULTIPLE COMPLETE | | FRACTURE TREATMENT | | ALTERING CASING | |
| SHOOT OR ACIDIZE | | ABANDON* | | SHOOTING OR ACIDIZING | | ABANDONMENT* | |
| REPAIR WELL | | CHANGE PLANS | | (Other) | | | |
| (Other) Status | | | | Completion or Reco | mile of multiple | completion on Well tand Log form.) | 1 |

17. DESCRIBE PROPOSED OF COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Completion work is continuing currently. Test Unit was installed 12-13-83 for formation evaluation. Service unit was released 11-4-83.

> RECEIVED JAN 1 6 1984 OIL COME DIV. DIST. 3

| 1 S. | hereby certify that the foregoing is true and correct | | | | |
|------|---|---------------------|------------|--------|--------|
| | SIGNED | TITLE District Adm. | Supervisor | DATE _ | 1-6-84 |
| ÷ | (This space for Federal or State office use) | | 1001297 | J FOR | Pacoro |
| | APPROVED BY COST THOUS OF APPROVAL, IF ANY: | TITLE | | DATE _ | |

*See Instructions on Reverse Side

| | Ι, | Assessed | ı dı. | Hannibhol | mach | |
|------|----|----------|-------|-----------|------|--|
| la v | | | | imm | | |