MERRION OIL & GAS CORPORATION

Canyon Largo Unit 336 Sec. 24, T25N, R6W Rio Arriba Co., New Mexico

SLOPE TESTS

Depth	Hole Deviation
589 1050	1/4° 1/4°

State of New Mexico	-	· ·	DIST STY.
County of San Juan)	33	· · · · · · · · · · · · · · · · · · ·

___, being first duly sworn, depose and state that I, Steve S. Dunn the above and foregoing depth and hole deviation figures are true and correct to the best of my information and belief.

day of June, 1984 Subscribed and sworn before me this $_{\perp}^{-28 \, {\rm th}}$