

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-039-23584
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Lease Name or Unit Agreement Name Boyt & Lola -A-
2. Name of Operator Oryx Energy Company	8. Well No. 2
3. Address of Operator P. O. Box 1861, Midland, Texas 79702	9. Pool name or Wildcat Gavilan Mancos
4. Well Location Unit Letter <u>D</u> : <u>790</u> Feet From The <u>North</u> Line and <u>790</u> Feet From The <u>West</u> Line Section <u>12</u> Township <u>2-W</u> NMPM Rio Arriba County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 7298' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7/25/90 POH w/rods & pump, POH w/2-7/8" tbg. to 4500'.

7/26/90 Set CIBP @ 6700'.

7/27/90 Circ. hole w/9.5#/gal mud, test csg to 750 PSI, OK.

7/28/90 Mud gelled in tbg., clean mud out of tbg, circ hole for 4 hrs, mud wt 8.9#/gal.

7/29/90 Bring mud wt up to 9.5#/gal, pumped 6 sx Class 'C' cmt, WOC 3-1/2 hrs, attempt to tag plug, no plug, press up on tbg., tbg plugged/ TOH, found cmt 26 jts off bottom.

7/30/90 Clean cmt out of tbg, replaced 11 jts, tagged CIBP, circ. mud, pump 6 sx cmt on CIBP.

7/31/90 Tag plug on CIBP, OK, POH to 5567', spot 20 sxs Cl. 'H' cmt 5567-5405', POH to 3583' & spot 60 sx. 3583 to 3100', POH to 225' & spot 30 sx. Cl. 'H' cmt 225' to surface, cut off csg 4' BGL, WOSP & marker, RR 7/30/90. Well P&A.

RECEIVED
AUG 06 1990
OIL CON. DIV.
DIST. 3

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Maria L. Perez TITLE Proration Analyst DATE 8-1-90

TYPE OR PRINT NAME Maria L. Perez TELEPHONE NO 915/688-0375

(This space for State Use)

Original Signed by **CHARLES GHOLSON**

APPROVED BY _____ TITLE DEPUTY OIL & GAS INSPECTOR, DIST. 3 DATE SEP 04 1990

CONDITIONS OF APPROVAL, IF ANY: