

KM PRODUCTION COMPANY
P.O. Box 2406
Farmington, NM 87401
(505) 325-6900

MALLON OIL COMPANY

FISHER FEDERAL #2-1
790' FNL & 790' FEL
Section 2, T25N, R2W
Rio Arriba County, New Mexico

SLOPE TEST

<u>DEPTH</u>	<u>DEVIATION</u>	<u>DEPTH</u>	<u>DEVIATION</u>
127'	3/4°	3061'	1½°
252'	3/4°	3315'	1¼°
500'	1¼°	4117'	1½°
756'	3/4°	4613'	2°
1003'	3/4°	5114'	3/4°
1251'	3/4°	5520'	1-3/4°
1406'	1½°	6023'	3/4°
1625'	3/4°	6521'	3/4°
1875'	1-3/4°	7022'	3/4°
2125'	2½°	7548'	1°
2375'	2½°	7674'	½°
2564'	2¼°	8143'	3/4°
2815'	2¼°	8397'	3/4°

[illegible]

RECEIVED
JUN 10 1985
OIL CON. DIV.
DIST. 3

I, Kevin H. McCord, Agent for Mallon Oil Company, being first duly sworn, depose and state the above and foregoing depth and hole deviation figures are true and correct to the best of my information and belief.

Subscribed and sworn before me this 6th day of June, 1985.

My Commission Expires: 9-20-88