



KM PRODUCTION COMPANY
P.O. Box 2406
Farmington, NM 87401
(505) 325-6900

MALLON OIL COMPANY
Howard 1-8
Section 1, T25N, R2W
Rio Arriba County, NM

RECEIVED
JUL 10 1985
OIL CON. DIV. 1
DIST. 3

SLOPE TEST

<u>Depth</u>	<u>Hole Deviation</u>	<u>Depth</u>	<u>Hole Deviation</u>
153'	1½°	3654'	1¼°
372'	2-¾°	4186'	1°
497'	2¼°	4558'	1¼°
660'	1½°	5061'	1°
909'	1¼°	5406'	1¼°
1158'	2¼°	5904'	1°
1322'	2¼°	6186'	1¼°
1503'	2¼°	6561'	1½°
1661'	2¼°	7055'	¾°
1908'	1-¾°	7413'	½°
2156'	1-¾°	8024'	1-¾°
2407'	1-¾°	8231'	1½°
2662'	1½°	8279'	1½°
3165'	¾°		

STATE OF NEW MEXICO)
) \$
COUNT OF SAN JUAN)

I, Kevin H. McCord, Agent for Mallon Oil Company, being first duly sworn, depose and state that the above and foregoing depth and hole deviation figures are true and correct to the best of my information and belief.

Kevin H. McCord

Subscribed and sworn before me this 9th day of July, 1985.

Eileen Hare
Notary Public

My Commission Expires: 9-20-88