



KM PRODUCTION COMPANY
P.O. Box 2406
Farmington, NM 87401
(505) 325-6900

MALLON OIL COMPANY

Howard #1-11
Sec. 1, T25N, R2W
1850' fSL & 1675' FWL
Rio Arriba County, NM

SLOPE TEST

<u>Deviation</u>	<u>Depth</u>	<u>Deivation</u>	<u>Depth</u>
1°	820'	1°	2874'
4°	1344'	1°	3356'
4°	1437'	1-3/4°	3610'
4 1/4°	1529'	1 1/2°	3857'
4 1/4°	1619'	1 1/2°	4133'
3-3/4°	1741'	1°	4409'
2-3/4°	1894'	1°	4931'
3 1/4°	2109'	1°	5424'
2-3/4°	2568'	1°	5945'
2 1/2°	2571'	1°	6529'
2°	2722'	1°	7817'
		2°	8032'

State of New Mexico)
County of San Juan) S

RECEIVED
NOV 04 1985
OIL CON. DIV.
DIST. 3

I, Kevin H. McCord, being first duly sworn, depose and state that the above and foregoing depth and hole deviation figures are true and correct to the best of my information and belief.

Kevin H. McCord
Kevin H. McCord, Agent for Mallon Oil Company

Subscribed and sworn before me this 1st day of November, 1985.

My Commission Expires: 9-20-88

Edison Hare
Notary Public