

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.  
30-039-24529

5. Indicate Type of Lease  
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION TO PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☒

GAS WELL ☐

OTHER

JUN 28 1990

2. Name of Operator  
Hixon Development Company

3. Address of Operator  
P.O. Box 2810, Farmington, N.M. 87499

7. Lease Name or Unit Agreement Name

Evans

8. Well No.  
1

9. Pool name or Wildcat  
Gavilan Greenhorn-Graneros-Dakota

4. Well Location  
Unit Letter D : 790 Feet From The North Line and 790 Feet From The West Line

Section 5 Township 24N Range 2W NMPM Rio Arriba County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
7115' GLE

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: Amended Drilling Progress ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spudded surface on January 15, 1990. Drilled 12-1/4" hole to 270'. Ran 6 jts. (249.38') of 9-5/8", 36#, ST&C casing. Baker-Lok notched collar on top of 1st jt. Ran centralizers on top of 1st and 3rd jts. Casing set at 264.88'. Mixed and pumped 170 sks. (200 cu. ft.) Class "B" cement containing 2% CaCl and 1/4#/sk. Cello Flake. Cement circulated to surface. Pressure tested casing to 600 psi for 30 minutes; test ok.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

John C. Corbett

TITLE Vice President-Exploration

DATE 6/28/90

TYPE OR PRINT NAME

TELEPHONE NO.

(This space for State Use)

APPROVED BY Original Signed by FRANK T. CHAVEZ

TITLE

SUPERVISOR DISTRICT III

DATE

JUL 18 1990

CONDITIONS OF APPROVAL, IF ANY: