



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Santa Fe**
Lease No. **SF 078724**
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	X
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 12, 1960

Zamera
Well No. **1-20** is located **660** ft. from **N** line and **1980** ft. from **E** line of sec. **20**
NE NW/4 Sec. 20 **24N** **6W** **NMPM**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Devils Fork Ext. **Rio Arriba** **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **6628** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded 12-1/4" hole at 4 P. M. 11-10-60. Drilling to 205'. Ran 190' of 8-5/8", J-55, 240, ST&C casing with guide shoe and set at 202'. Cemented w/125 sx reg. w/2% CaCl₂. POB at 8:15 A. M. 11-11-60. After 18 hrs. tested w/1050 psi for 30 min., no pressure drop. Drilling 7-7/8" hole to 5585'. Ran Schlumberger induction, sonic logs to T. D. Ran 177 jts. 4-1/2" 9.55 J-55 8 Rd ST&C casing. T. E. 5571.50' set at 5579'. Cemented w/100 sx cement w/6% gel & 30 sx reg. POB at 12:00 midnight 11-24-60. After 18 hrs. tested w/1400 psi for 30 min. No pressure drop. RR, waiting on completion rig.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Val R. Reese & Associates, Inc.**Address **Lobby of Simms Bldg.****Albuquerque, New Mexico**By *Lewis C. Jamison*Title **Geologist**