
	D STATES OF THE INTERIOR	5 LEASE NM 0149964-A
GEOLOGI	CAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AN	ND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir, Use Form 9-331-C for such proposals.)		8. FARM OR LEASE NAME
		Blakely 23
1. oil 🔯 gas 🗆 ott	ner	9. WELL NO.
2. NAME OF OPERATOR Grace Petroleum Corporation  3. ADDRESS OF OPERATOR 1515 Arapahoe Street 3 Park Central, Ste. 333, Denver, CO 80202		6
		10. FIELD OR WILDCAT NAME
		Escrito Lybrook Field
		11. SEC., T., R., M., OR BLK. AND SURVEY OF
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17		AREA
below.)		Sec. 23, 124N, R/W
	FNL & 1120' FWL	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL:	Same.	Rio Arriba   New Mexi∞
AT TOTAL DEPTH:	Same	14. API NO.
16. CHECK APPROPRIATE BOX		
REPORT, OR OTHER DATA		15. ELEVATIONS (SHOW DF, KDB, AND WD
· ·		6752¹_GL
REQUEST FOR APPROVAL TO:	SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF FRACTURE TREAT		IVED \
SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF	(NOTE) Report results of multiple completion or zon  y () change on Form 9-330.)
PULL OR ALTER CASING [	□ i □	ა • <b>წ</b>

(other) Subsequent report to reclaim pit.

1. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

1) Pit has been reclaimed and is ready for inspection.



Subsurface Safety Valve: Manu. and Type		Set @ Ft.
18. I hereby certify that the foregoing is to SIGNED DONALD C. Smith	TITLE Sr. Oper. Engineer DATE Ju	ne <u>7</u> , 1983
	(This space for Federal or State office use)	
APPROVED BY	TITLE DATE	

- - BELUWE

\*See Instructions on Reverse Side

JUN 1 1983

MULTIPLE COMPLETE CHANGE ZONES ABANDON\*

