


(SUBMIT IN TRIPLICATE)

Indian Agency Navajo

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Allottee 14-20-603-2202  
Lease No. 14-20-603-2202



Sec. 5

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Dec. 23, 1953

19

Well No. 1 is located 990 ft. from N line and 970 ft. from E line of sec. 5

5  
(1/4 Sec. and Sec. No.)

17 W  
(Range)

107 W  
(Meridian)

Wilcox  
(Field)

San Juan County  
(County or Subdivision)

New Mexico  
(State or Territory)

The elevation of the derrick floor above sea level is 5725 ft.


DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Hole drilled to 3507' TDC, and logged with no shows. Cement plugs were spotted at the following points:

- Plug #1 - 3550' to 3650' w/30 sac cement
- Plug #2 - 3650' to 3750' w/30 sac cement
- Plug #3 - 380' to surface w/10 sac cement

Placed 6" of 1 1/2" LF in top of cement extending 4' above ground level. Pits filled and location marked.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Lawrence Drilling Co., Inc.  
2714 E. 16th St.  
Address Farmington, N. M.

By James H. Lawrence  
Lawrence Drilling Co., Inc.  
Title President