

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe  
Lease No. 078869  
Unit Sapp

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	X
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

4-1, 19 63

Well No. 1 is located 1450 ft. from N line and 965 ft. from E line of sec. 30  
SE/4 Sec. 30 24N 8W N.M.P.M.  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Wildcat San Juan County New Mexico  
(Field) (County or Subdivision) (State or Territory)


The elevation of the derrick floor above sea level is 6916 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

This well has been plugged and abandoned in the following manner:

1. Perforations from 5326- 5341 were squeezed w/30 sx cement.
2. 5 1/2" casing found to be free @ 2475' and same recovered.
3. Placed 35 sx plug across stubs from 2475 to 2500.
4. Placed 85 sx plug from 1900 to 1650.
5. Erected P & A Marker W/108 sx surface plug.



RECEIVED  
JUN 27 1963

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Dorfman Production Company  
Address 836 Mercantile Dallas Building  
Dallas 1, Texas

By Larry A. Bedford  
Title Agent for Operator