

Santa Fe

(SUBMIT IN TRIPLICATE)

Land Office

SF-079712-C

Lease No. _____

Unit:

Ge. Loc. No. 239549

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

X			

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

TAMPA UNIT

Farmington, New Mexico December 20 1957

Well No. 1 is located 1010 ft. from ~~XXXX~~ line and 970 ft. from ~~XXXX~~ line of sec. 21
SW/4 Section 21 1-24-N 8-12-W

(1/2 Sec. and 1 Sec. No.)
Tender Unit

(Twp.)

(Range)

(Meridian)

New York 60

(Field)

(County or Subdivision)

(State or Territory)

The elevation of the derrick floor above sea level is 6087 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Verbal approval received 12-12-57.

Intention: Pull tubing, remove packer, run Baker GI cement retainer at 2800', squeeze perforations from 2870' - 2878' w/75 sacks cement. Set top plug and permanent markers.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Humble Oil & Refining Company

Box 1268

Address Farmington, New Mexico

COPY ORIGINAL R. M. LILLY
SIGNED:
By Russell W. Lilly
Agent

Title

A handwritten signature in dark ink, appearing to be "W. J. ...". The letters are cursive and somewhat stylized.