

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe  
Lease No. SP-079046  
Unit Pennin-white  
Co. 1 Woodard

SUNDRY NOTICES AND REPORTS ON WELLS


NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....	<input checked="" type="checkbox"/>		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 10, 1956

Well No. 1 is located 660 ft. from [N] line and 640 ft. from [E] line of sec. 13

NE 1/4 Sec. 13 T-21-N R-10-W N.M.P.M.  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
New Mexico  
(Field) (County or Subdivision) (State or Territory)



The elevation of the derrick floor above sea level is 6275 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well plugged and abandoned September 2, 1956, as follows:

10 sacks cement at top of hole

Cement over following intervals:

350' to 450'  
1150' to 1250'  
1900' to 2000'  
3850' to 3950'  
4500' to 4750'

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

~~Company~~ J. L. Pennin, Jr.

Address 115 Seventh St., N.  
Albuquerque, New Mexico

By [Signature]  
Title Principal