



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe  
Lease No. NM-088040A  
Unit Nancy Federal

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	X
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 26, 1961

Well No. 3 is located 990 ft. from XX line and 1793 ft. from XX line of sec. 12  
SE/4 SW/4 Sec. 12 24N 8W N.M.P.M.  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Escrito (Gallup) San Juan New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 7212 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

12/22/61 - Plugged and abandoned well. Set plugs, as follows:

5840 - 5940' - 35 sacks cement  
 3250 - 3350' - 35 sacks cement  
 2400 - 2500' - 35 sacks cement

Top of surface casing - 10 sacks cement with  
 identification pole above ground.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Dorfman Production Company

Address 836 Mercantile Dallas Building

Dallas 1, Texas

By S. L. Florsheim, Jr.  
S. L. Florsheim, Jr.  
 Title General Manager