

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R359.4
Approval expires 12-31-60.
Indian Agency Nevada Agency
Window Rock, Arizona
Allotted Wairs of Hostain-tail,
et al 2-149-Ind.-9217
Lease No. _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

MAR 10 1959

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 9,

Well No. 1 is located 1900 ft. from [N] line and 660 ft. from [E] line of sec. 11
SW/4 Section 11 24 North 9 West 187N
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
wildcat San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)


The elevation of the derrick floor above sea level is 6647 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casing; indicate mudding jobs, cementing points, and all other important proposed work.)

Cement plugs were run as follows:

5000-5150	45 sacks
4250-4350	30 "
3150-3250	30 sacks
1650-1750	30 "
225-275	15 "
Surface	5 "



Hole is full of heavy mud. Location has been cleaned, leveled & marker erected.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company KERN COUNTY LAND COMPANY

Address 304 Karber Building

Albuquerque, New Mexico

By John S. Baker
Title District Geologist