


(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office San Antonio

Lease No. 87-272832

Unit \_\_\_\_\_



Sec. 7

SUNDRY NOTICES AND REPORTS ON WELLS

RECEIVED  
AUG 1 1957  
U. S. GEOLOGICAL SURVEY  
FARMINGTON, NEW MEXICO

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 31, 1957

Well No. 7-1 is located 1080 ft. from N line and 600 ft. from W line of sec. 7

San Antonio  
(1/4 Sec. and Sec. No.)

San Antonio  
(Twp.)

San Antonio  
(Range)

N. M. Principal  
(Meridian)

San Antonio Area  
(Field)

San Juan County  
(County or Subdivision)

New Mexico  
(State or Territory)

The elevation of the derrick floor above sea level is 5892 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

The San Antonio Federal #7-1 was studied on July 30, 1957. On the second day, a 3/8" surface casing, was set at 400 ft. and cemented with 300 gal of cement. On the last day of July operation was drilling at 600 feet.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Standard Oil Company of Texas

Company \_\_\_\_\_

Address P. O. Box 1240

San Antonio 1, Texas

By [Signature]

Title General Engineer