

(SUBMIT IN TRIPLICATE)

 UNITED STATES
 DEPARTMENT OF THE INTERIOR
 GEOLOGICAL SURVEY
Land Office **Santa Fe**Lease No. **NM 014580-A**

Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	X
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)


October 9, 1961

Well No. **Ake 1-11** is located **2440** ft. from **NE** line and **540** ft. from **E** line of sec. **11****NE SE** Sec. 11
(1/4 Sec. and Sec. No.)**24N**
(Twp.)**SW**
(Range)**NMPM**
(Meridian)**Escrito-Gallup Ext.**
(Field)**San Juan**
(County or Subdivision)**New Mexico**
(State or Territory)The elevation of the derrick floor above sea level is **7195** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded 12 1/2" hole at 12:30 AM, 10-4-61. Drilled to 208'. Ran 197.79' of 8-5/8", 24#, J csg. and set at 204'. Cemented with 130 sacks of cement w/3% CaCl₂. PoB @ 9:45 AM 10-4-61.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Marvin Ake c/o Val R. Reese & Associates, Inc.**Address **Lobby of Simms Building****Albuquerque, New Mexico**Original Signed by
By **MORRIS B. JONES** **Morris B. Jones**Title **Engineer**