

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE  
(Other instructions on re-  
verse side)Form approved  
Budget Bureau No. 42-R1424

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. <b>SF 78301</b>
2. NAME OF OPERATOR <b>Skelly Oil Company</b>		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR <b>1860 Lincoln St. - Denver, Colorado 80203</b>		7. UNIT AGREEMENT NAME <b>East Bisti Unit</b>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface  <b>660' FNL &amp; 660' FWL Section 12-24N-10W</b>		8. FARM OR LEASE NAME
14. PERMIT NO.		9. WELL NO. <b>106</b>
15. ELEVATIONS (Show whether DF, RT, GR, etc.) <b>6920' DF</b>		10. FIELD AND POOL, OR WILDCAT <b>Bisti-Lower Gallup</b>
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <b>Section 12-24N-10W</b>
		12. COUNTY OR PARISH <b>San Juan</b>
		13. STATE <b>New Mexico</b>

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐PULL OR ALTER CASING ☐FRACTURE TREAT ☐MULTIPLE COMPLETE ☐SHOOT OR ACIDIZE ☐ABANDON\* ☐REPAIR WELL ☐CHANGE PLANS ☐(Other) Assignment of well to Church ☒

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐REPAIRING WELL ☐FRACTURE TREATMENT ☐ALTERING CASING ☐SHOOTING OR ACIDIZING ☐ABANDONMENT\* ☐(Other) ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

## 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

All depths shown are from ground level.

8/17/71 - MI & RU Aztec Well Service Unit. Pulled all rods. Spotted cement plug from 5508' to 5408'. Perforated 5½" casing at 1864'. Set cement plug inside and outside 5½" casing from 1864' to 1714'. Perforated 5½" casing at 1200'. Set cement plug from 1200' to 1100', inside and outside 5½" casing. Job complete 11/30/71.

This well is being left in condition to be produced for water source.

An assignment to the Brethern in Christ Mission, Inc. - Bloomfield, New Mexico will be made by Skelly Oil Company on the termination date of the East Bisti Unit.

## 18. I hereby certify that the foregoing is true and correct

SIGNED

*C. L. B. B.*TITLE **Lead Clerk**

DATE

**December 8, 1971**

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: