

APPROVED SEP 11 1956 JERRY W. LONG ACTING DISTRICT ENGINEER	(SUBMIT IN TRIPLICATE)
	UNITED STATES
	DEPARTMENT OF THE INTERIOR
	GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. S.F. 07122
Unit Hemel Belack

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	<u>C. S. T. No. 4</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Hemel Belack

July 31, 19 56

Well No. 1 is located 660 ft. from 2000 [S] line and 660 ft. from [E] [W] line of sec. 5

25/4-35/4 Section 5 24 11 N. H. P. 4
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Mendian)


Eldest San Juan Box 426
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6388 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casing; indicate cementing jobs, cementing points, and all other important proposed work)

C. S. T. No. 4 Packer set at 4544' - T. D. 4605'
Tool opened 1 hr. - very slight blow of air - died within 10 min. Pulled tool
recovered 15' drg. sand. I.P. 655' - F.P. 655' Shut in 30 min. Bottom hole
pressure 655' - Hyd. head pressure in-2400' - Hyd. head pressure out-2465'



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Shelly Oil Company

Address Box 426

Farlington, New Mexico

By [Signature]

Title District Foreman