



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office San AntonioLease No. 030167

Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 21, 1956

Well No. 51101 is located 2045 ft. from SW line and 660 ft. from E line of sec. 1

Sec. 1 (1/4 Sec. and Sec. No.) 24 N (Twp.) 11 W (Range) 6th P.M. (Meridian)
Alameda (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 6715.0 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

T.D. 5191. Set plugs at these depths:
4950 to 5100 with 40 sacks; 3950 to 4050 with 35 sacks;
1700 to 1800 with 35 sacks; 1350 to 1500 with 30 sacks;
0 to 10 with 5 sacks; Erected regulation marker in top
at 10-3/4. Heavy viscosity mud spotted between cement
plugs; Location cleaned and pits backfilled.



I understand that this plan of work must receive approval in writing by the Geological Survey before operation may be commenced.

Company C. M. & P. DRILLING COMPANY

Address 1440 South Santa Fe Drive
Denver 22, Colorado

By L. J. ThorntonTitle Drilling Superintendent

