

Sante Fe


(SUBMIT IN TRIPLICATE)

Land Office _____

Lease No. 078531A

Unit _____

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	1959
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	Casing Reports	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)


Well No. 2 is located 1050 ft. from [N] line and 850 ft. from [E] line of sec. 3
 (1/4 Sec. and 1/4 No.) (Twp.) (Range) (Meridian)
 Antelope (County of Union) N Mex (State or Territory)

The elevation of the derrick floor above sea level is 7198.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

200' 9 5/8" 34# Spang Casing set by Halliburton with 200 Sax
 7237' 58" 15# CP&I Casing set by Halliburton with 451 Sax



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company ROYAL DEVELOPMENT CO.

Address Box 1299 Albuquerque N Mex

By H. E. Skilleander

Title Agent