


(SUBMIT IN TRIPLICATE)

Land Office Santa Fe
Lease No. SV-075076
Unit _____



UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 1, 1956

Well No. 1 Hins Canyon situated 660 ft. from N line and 702 ft. from E line of sec. 4
34 (1/4 Sec. and Sec. No.) 24 (Twp.) 12 (Range) 12 (Meridian)
Wilcox (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 6202 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

The well was spudded 12-3-56.

120' of 9-5/8" casing was cemented and circulated with 100 sacks.
Before drilling the plug the casing was pressured up to 500 lbs. for 30 minutes with no drop in pressure. After drilling the plug, the casing was again pressured up to 500 lbs. for 30 min. with no drop in pressure.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Kenneth Murchison
Address 1315 Pacific Ave.
Dallas, Texas

By [Signature]
Title Agent

