

		X	

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office New Mexico
Lease No. SF 078623
Unit Scott

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	X
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 14, 1957

Well No. 1 is located 660 ft. from N line and 1980 ft. from E line of sec. 4
26N 10W NMPM
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Gallup San Juan New Mexico
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 7169 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spd 12/29/56

10-3/4" @ 170 w/200; 5-1/2" @ 5475 w/200; 2" @ 5290

Perf 5158-5160, 4 holes (squeezed); Sand-oil Fractured 5319-5325 w/20000 G, 20000#
 Sand-oil Fractured 5349-5358 w/20000 G, 20000 #;

Casing and water shut-off were tested w/500# pressure for thirty minutes, no drop in pressure.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Moore, Moore and Miller
 Address 2904 Liberty Bank Building
Oklahoma City, Oklahoma

By [Signature]
 Title Agent-Owner

