

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
E-3147

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Water Injection	7. Unit Agreement Name
2. Name of Operator	8. Farm or Lease Name
Skelly Oil Company	
3. Address of Operator	9. Well No.
1860 Lincoln Street - Denver, Colorado 80203	86
4. Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER B 660 FEET FROM THE North LINE AND 1980 FEET FROM	Bisti Lower Gallup
THE East LINE, SECTION 2 TOWNSHIP 24 N RANGE 10 W NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
6786' DF	San Juan

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:


SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

All depths shown are from Ground Level.

8/31/71 MI&RU Aztec Well Service Unit. No rods in hole. Spotted cement plug from 5419' to 5319'. Pulled 2" tubing. Worked 5 1/2" casing to free same. Rigged up Blue Jet, perforated from 1744' to 1745' w/4 shots. Ran 2" tubing. Spotted cement plug from 1745' to 1595'. Pulled 2" tubing. Shot 5 1/2" casing off at 1059'. Spotted cement plug from 1745' to 1595'. Pulled 2" tubing. Shot off 5 1/2" casing at 1059'. Spotted cement plug from 1109' to 940', 50' below casing stub and 119' above casing stub. Pulled total of 33 joints 1064' of 5 1/2" casing. Spotted 10' cement plug in surface casing. Installed dry hole marker. Completed P&A 8/31/71.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Lo. L. Birk</u>	TITLE <u>Lead Clerk</u>	DATE <u>December 10, 1971</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>SUPERVISOR DIST. #3</u>	DATE <u>12-15-71</u>
CONDITIONS OF APPROVAL, IF ANY:		

86
B 2-24N-10

NEW MEXICO OIL CONSERVATION COMMISSION
1000 RIO BRAZOS ROAD
Aztec, New Mexico

Skelly Oil Co
1560 Lincoln ST
Denver, Colo 80203

RE: Plugging Reports

Gentlemen:

Form C-103, Notice of Intention to Plug, your East Bist. Unit 86 B 2-24N-10W
Lease Well No. Unit- S-T-R
was approved on 7-22-71. Your subsequent notice of plugging cannot be
approved until a commission representative has made an inspection of the location
to see:

- (1) all pits have been filled and leveled;
- (2) a steel marker, 4" in diameter and approximately 4' above mean ground level, must be set in concrete, this marker must have the quarter-quarter section or unit designation, section, township and range numbers, which shall be permanently stenciled or welded on the marker;
- (3) the location shall be cleared and cleaned of all junk;
- (4) the dead man wires must be cut.

The above are the minimum requirements.

Please notify us by filling in the blank form below when this work has been done so that our representative will not have to make more than one trip to the location.

OIL CONSERVATION COMMISSION

By Emily C. [Signature]

Fill in below and return:

Lease Well No. Unit-S-T-R

is ready for your inspection and approval.

Operator

Name and title

Location Inspected
OK C R K
12-6-71