L

Form 9–331	5 USGS,	<sup>_</sup> m <b>n</b>	1 NWPL	2 1	MF 1	FileForm	Appro	ved.		
Dec. 1973	UNITED DEPARTMENT OF		R		5. LEASE NM 1658		et bure	eau No. 42-F		
	GEOLOGICA					6. IF INDIAN, ALLOTTEE OR TRIBE NAME				
		······	<del></del>				•	5 .74		
	Y NOTICES AND				7. UNIT AG	REEMENT N	AME	Ξ. Ξ		
reservoir. Use Fo	rm 9-331-C for such propo	sals.)	oack to a diner	-	8 FARM OF	R LEASE NAM	15			
1. oil	gas 🖂				Mountai	n :	·		<del></del>	
well U					9. WELL NO	). -	-	20 12 - 12 - 12 - 12 - 12 - 12 - 12 - 12 -		
2. NAME OF	OPERATOR			_	4					
DUGAN PRODUCTION CORP.					10. FIELD O	R WILDCAT N	IAME	<u></u>		
3. ADDRESS OF OPERATOR					Undesig	nated -	PC -			
	208, Farmington,	NM 87401			11. SEC., T.,	R., M., OR E	BLK. A	ND SURVE	YOR	
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17					AREA		•	3		
below.)					Sec 14	T24N- R8W				
AT SURFA	ACE: 1850' F	SL - 850' FV	JI		12. COUNTY			STATE '		
AT TOP PROD. INTERVAL:					San Jua	_	:	NM -		
AT TOTAL	DEPTH:				14. API NO.		-			
16 CHECK A	PPROPRIATE BOX TO	INDICATE NATU	RE OF NOTIO		- 11 /11 / 1101	12	٠,			
	OR OTHER DATA			-	15. ELEVATI	UNE (CHUM	DE	KDB VND	WD	
•				ŀ	6900' G		υ, 	NUB, AND	WU)	
REQUEST FOR	R APPROVAL TO:	SUBSEQUENT	REPORT OF:	L	0300 0	IL .		7.4		
TEST WATER		Ī								
FRACTURE TE	REAT					عَ اللَّهِ عَلَيْهِ اللَّهِ عَلَيْهِ عَلَيْهِ عَلَيْهِ عَلَيْهِ عَلَيْهِ عَلَيْهِ عَلَيْهِ عَلَيْهِ	<b>5</b> 1	100		
SHOOT OR A							:			
REPAIR WELL					(NOTE: Flepo	rt results of mu	iltiple o	ompletion o	rzone	
	TER CASING				chan	ge on Form 9-	330.)	-	•	
MULTIPLE CO		Ц			•	<u> </u>	_		<u>.</u>	
CHANGE ZON	ES 📙						-	٠.		
ABANDON*	L	LXIX				• •		<i>:</i>	• •	
(other)								· 1	*	
including	E PROPOSED OR COM estimated date of star d and true vertical depth	ting any proposed is for all markers a	work. If well and zones pert	is dire linent l	ectionally dril to this work.)	led, give sub	give surfac	pertinent of locations	lates, s and	
	Plugged and aba	ndoned as fo	llows:	7-	- 30 8		7186 3			
	1. Filled 2-7/	8" OD, 6.5#,	.1-55 8R	иR	" tubing	for rasi	nα			
	using AA sy	class "B" n	eat comen	, d.	baselasi	with 1 h	119 -	frach		
	water. Clo		eut temen	c, u	rspraced	WICH 2 D	21 4.7	11.6311		
			hala man		1	- 문화 기약원	=	() 医甲基基		
		ermanent dry	note mont	umen	ι	그 원인 현결	7	5 <del>4</del> 9 4		
	3. Filled all			_		្តីត្ <sub>ន</sub> ិទី		ع ۾ ا		
	4. Cleaned wel	1 location o	t all equi	ipme	nt, pipe,	junk, a	nd t	rash.		
		m surface re					surf	ace 📑		
	management	agency or la	ndowner ne	ext p	planting	season.				
	6. Cut off tie	-downs.		•		्नं का रही है।	•	·		
Subsurface Sa	afety Valve: Manu. and 1	уре				Set	@	- 0 4	Ft.	
18. I hereby o	ertify that the foregoing	is true and correc	t				; ·•			
	1 1 VV	TITLE	Geologi	ist		10-4-8	2 .			
SIGNED	//mx 1	TITLE	20109		DATE	10 T U		दि हिन्द्रम् सम्	Pr Cheffo	

OIL CON. DIV. DIST. 3

(This space for Federal or State office use)

\_ TITLE \_

\_ DATE \_