

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
L-2986	
7. Unit Agreement Name	
NONE	
8. Form or Lease Name	
NEW MEXICO STATE	
9. Well No.	
#2	
10. Field and Pool, or Wildcat	
Nageezi-Gallup	
12. County	
San Juan	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input checked="" type="checkbox"/>	GAS WELL <input type="checkbox"/>	OTHER- <input type="checkbox"/>
Name of Operator		
KENAI OIL AND GAS INC.		
Address of Operator		
717 17th Street, Ste. 2000, Denver, CO 80202		
Location of Well		
UNIT LETTER	M	950
FEET FROM THE South LINE AND 980 FEET FROM		
THE West	LINE, SECTION 32	TOWNSHIP 24N RANGE 8W

15. Elevation (Show whether DF, RT, GR, etc.)  
6945' GL

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK	<input type="checkbox"/>	PLUG AND ABANDON	<input type="checkbox"/>
TEMPORARILY ABANDON	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
NULL OR ALTER CASING	<input type="checkbox"/>	OTHER	<input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
COMMENCE DRILLING OPNS.	<input type="checkbox"/>	PLUG AND ABANDONMENT	<input type="checkbox"/>
CASING TEST AND CEMENT JOBS	<input type="checkbox"/>	OTHER	<input checked="" type="checkbox"/>

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Ran surface casing as follows: Ran 7 jts, 8-5/8", 23#, J-8RT-STC-R3 new casing w/guide shoe & insert float measuring 295.31' & landed @ 310.31'KB. Cemented w/250 sxs, Class B cement + 3% CaCl and 1/4#/sx. Cello-Flake. Bumped plug w/600 psi @ 9:15 a.m., 7/21/80. Lost pump pressure immediately and pipe jumped up 1' and fell back as landed. Cement fell 3' on outside of casing. Full returns while cementing. NU BOP and tested with 1000 psi held o.k. after 18 hours.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Signed by George B. Judd TITLE Manager-Drilling & Production DATE August 19, 1980

Original Signed by FRANK T. CHAVEZ

SUPERVISOR DISTRICT #3

AUG 25 1980

NOTED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:  
Notify this office of cement amount as well as drilling out