6 BLM 1 - Tenneco	1 - McHugh 1 - File
Form 9–331 Dec. 1973	Form Approved. —Budget Bureau No. 42-R1424
UNITED STATES	5. LEASE 필리일을 표 중요한
DEPARTMENT OF THE INTERIOR	NM 14100 일립률사 🚊 목통률
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
• •	Mean Betty Jean
1. oil gas XX other	9. WELL NO. 2 13 4 4 13
2. NAME OF OPERATOR	1 अभिनेत्र स विनेत्र
Dugan Production Corp.	10. FIELD OR WILDCAT NAME = 5.5
3. ADDRESS OF OPERATOR	Chacra Wildcat
P O Box 208, Farmington, NM 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA STATES STATES
below.)	Sec 14 T24N R11W =
AT SURFACE: 1850' FNL - 790' FEL	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL:	San Juan 목사를링트 및 문NM
AT TOTAL DEPTH:	14. API NO. 호롱트램 크 호물족리
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	विज्ञान ह प्रविद्
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DE KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	6510' GL 3075 8 5539
	0 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
TEST WATER SHUT-OFF U U FRACTURE TREAT U	सुर्वे हैं के जिल्हा है। जुड़े हैं व
SHOOT OR ACIDIZE	
REPAIR WELL	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING	change on Form 9-330.
MULTIPLE COMPLETE GUANGE ZONES	
CHANGE ZONES LI LI ABANDON* NO KX	를 하는 전 기계 1984 · · ·
(other)	z = z + z + z = z
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stat including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertiner	lirectionally drilled, give subsurface locations and
	କୁ ଅଧିକୁ ଛିଟା ଓଡ଼ି କିମ୍ବି
Plugged and Abandoned as follows: $5-/-84$	គ្នីគេភូមិ្ត មួយជាក់ស៊ី
1. Filled 2-7/8" casing from PBTD 1746' to s	The state of the s
Installed dry hole marker.	DECEIVE
Filled pits.	03 1984
4. Cleaned and restored location per BLM ins	struction.
Cut off or removed tie-downs.	्रिक्ति हुन है के 174 pist. 3 इंड विश्व है है है जिस्सी
Subsurface Safety Valve: Manu. and Type	
18. I hereby certify that the foregoing is true and correct	
Coologist	PATE = 15 6-25-84 3 4 3 4 3 4 3 4 3 4 3 4 3 4 3 4 3 4 3
Sherman E. Dugan	DATE
(This space for Federal or State off	fice use) - 구설성공업 스타 교육실업
APPROVED BY TITLE	
CONDITIONS OF APPROVAL, IF ANY:	

NMOCC