

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other2. NAME OF OPERATOR
DUGAN PRODUCTION CORP.3. ADDRESS OF OPERATOR
P O Box 208, Farmington, NM 87401

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 1520' FNL - 790' FEL

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

☐ TEST WATER SHUT-OFF
☐ FRACTURE TREAT
☐ SHOOT OR ACIDIZE
☐ REPAIR WELL
☐ PULL OR ALTER CASING
☐ MULTIPLE COMPLETE
☐ CHANGE ZONES
☐ ABANDON*
(other) ☐

SUBSEQUENT REPORT OF:

RECEIVED
FEB 11 1982
U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.
XX Spud & surface casing

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

2-13-82 MI & RU Four Corners Drilling Co. Rig #10. Spudded 12 1/4" hole at 12:30 p.m. 2-12-82. Drilled to 215. Ran 5 jts. 8-5/8" O.D., 24#, 8 RD, ST&C csg. T.E. 189.41' set at 201' RKB. *KB 12' above L*Cemented with 135 sx class "B" plus 2% CaCl. (159 cu.ft.)
P.O.B. at 5:00 p.m. 2-12-82. Cement circulated.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Thomas A. Dugan TITLE Petroleum Engineer DATE 2-15-82

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

MAR 01 1982

*See Instructions on Reverse Side

NMOCC

FARMINGTON DISTRICT