

SUNDRY NOTICES AND REPORTS ON WELLS

1. oil well ☐ gas well ☒ other

R. E. Lauritsen

3. ADDRESS OF OPERATOR

P.O. Box 2364

AT SURFACE: 2110' FSL & 330' FEL

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

PULL OR ALTER CASING

MULTIPLE COMPLETE

CHANGE ZONES

ABANDON*

(other) Plug

SUBSEQUENT REPORT OF

REPORT OF
RECEIVED
202

OCT 27 1982
(N)

U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

9-7-82-----Request to Plug Well

DEPTH

1386' - 670'-----Cement with 85 Sacks

670' - Surface-----Cement with 10 Sacks

	TOPS	
<u>Formation</u>	<u>Depth</u>	<u>Content</u>
Picture Cliff	705	Salt Water
Chacra	1080	Water

Subsurface Safety Valve: Manu. and Type

18. I hereby certify that the foregoing is true and correct

SIGNED R. E. Lawrence TITLE Operator

DATE _____

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: _____

NMOCC

"See Instructions on Reverse Side"

APPROVED

OCT 23 1982

JAMES F. SIMS
DISTRICT ENGINEER