Form 3169-5 5 BL	UNITED STATES	SUBMIT IN TRIPLICATE			
(November 1983) (Formerly 9–331)  DEPARTMENT OF THE INTERIOR (Other instructions on re- BUREAU OF LAND MANAGEMENT			5. TEASE DESIGNATION AND SERIAL NO. NM 36473		
					SUNDRY NO
1.		/	7. UNIT AGREEMENT NA	ME	
OIL GAS OTHER					
2. NAME OF OPERATOR			8. FARM OR LEASE NAM		
Dugan Production 3. ADDRESS OF OPERATOR	corp.		WAC 9. WHILE NO.		
	mington, NM 87499		1 1		
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*			10. FIELD AND POOL, OF	10. FIELD AND POOL, OR WILDCAT	
See also space 17 below.) At surface			Basin Dakota		
790' FNL - 890' FWL APR 051985		11. SEC., T., E., M., OR BLK. AND SURVEY OR ARMA			
	APK	V 3 13 03	Sec. 17, T24N	i, R9W, NMP!	
14. PERMIT NO.	15. ELEVATIONS (Show whether BF.	87.6h.eta.hr. April	12. COUNTY OR PARISH	18. STATE	
14. PERSIT NO.	6750' GL: 676	•	San Juan	l <sub>NM</sub>	
	<u></u>	_		<u> </u>	
16. Check A	appropriate Box To Indicate No				
NOTICE OF INTENTION TO:			UBNT REPORT OF:		
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING V		
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CA	[]	
SHOOT OR ACIDIZE	ABANDON* CHANGE PLANS	SHOOTING OR ACIDIZING (Other)	Plug Back	X	
REPAIR WELL (Other)		(Note: Report result	s of multiple completion pletion Report and Log for	on Well	
on wire bailer. product	with tubing and rods. line. Dumped 50' ceme Landed tubing at 550 ion from the Gallup fo .T.D. of 6239'.	nt on top bridge plu 9' RKB. Ran rods au	ug with wireline nd returned to	!	
			4 - A	્રક્ષે	
				<u></u>	
			(-1/1)	<i>‡</i>	
				, vi	
18. I hereby certify that the foregoing	is true and correct				
SIGNED /	TITLE G	eologist	DATE4-4	1-85	
(This space for Federal or State of	ODS lice use)	Fig.		<del></del>	
•	TITLE		PATE:		
CONDITIONS OF APPROVAL, IF			TAPE TO THE		
	••		maneus ou an anna e	ξι Σηγέ	
	*See Instructions	on Reverse Side RV			