MERRION OIL & GAS CORPORATION

Federal A No. 3
Sec. 10, T24N, R8W
San Juan Co., New Mexico

SLOPE TESTS

Depth		Hole Deviation
228	**	1/2
1336		1/2
1836		3/4
2303		1
2404		2-1/2
2830		2
3437		3/4
3930		3/4
4412		1
4930		1-3/4
5438		1
5981		1



State of New Mexico			
County of San Juan)	SS	

I, Steve S. Dunn, being first duly sworn, depose and state that the above and foregoing depth and hole deviation figures are true and correct to the best of my information and belief.

Subscribed and sworn before me this

day of

atrick bases T

My Commission Expires Dec. 11, 1989