T.I.H. with 15	¦" OD tubing landed @ 1	752 ' .	REGETTED
T.I.H. with 1	¼" OD tubing landed @ 1	752'.	
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other)	PCLL OR ALTER CASING MULTIPLE COMPLETE ABANDON* CHANGE PLANS OPERATIONS (Clearly state all pertine) ectionally drilled, give subsurface local	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) [Note: Report resu Completion or Recon	Tubing Tubing ALTERING CASING ABANDONMENT® X Its of multiple completion on Well appletion Report and Log form.) es, including estimated date of starting any circul depths for all markers and gones perti-
14. PERMIT NO.	15. ELEVATIONS (Show whether D 6905' G		San Juan NM
	on clearly and in accordance with any	State requirements.*	10. FIELD AND FOOL, OR WILDCAT Undesignated Pictured Cliffs 11. SHC., T., R., M., OR BLK. AND BURNEY OR ABBA Sec. 30, T24N, R8W, NMPM
2. NAME OF OPERATOR DUGAN PRODUCTION CORP. 3. ADDRESS OF OPERATOR P.O. Box 5820, Farmington, NM 87499 -5820			9. WELL NO.
			8. FARM OR LEASE MAME Buddha Temple
it this form for the	opposals to drill or to deepen or plug LICATION FOR PERMIT—" for such p	back to a different reservoir.	7. UNIT AGREEMENT NAME
SUNDRY NOTICES AND REPORTS ON WELLS			6. IF INDIAN, MLOTTEE OR TRIBE NAME
BUR	RTMENT OF THE INTER		5. LEASE DESIGNATION AND BERIAL NO.

*See Instructions on Reverse Side