

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. NM 01806
Unit Gardiner

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 30, 1962, 19__

Well No. 2 is located 890 ft. from EX line and 890 ft. from EX line of sec. 28
SW 1/4 Sec. 28 26N 2W NM PM
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Govilan PC Rio Arriba New Mexico
 (Field) (County or Subdivision) (State or Territory)


The elevation of the derrick floor above sea level is 7482 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

This well was plugged and abandoned in the following manner:

1. Perforations covered with cement.
2. Cut off 4 1/2" casing at 2210'. Spot with 100' cement plug, 2160-2260.
3. Set cement plug at base of surface pipe.
4. Set 10 sack plug at top of surface pipe with 5 foot marker.
5. Cleaned and graded location.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company John A. Egan

Address P. O. Box 208

Farmington, N.M.

By John A. Egan Jac
Title Operator