

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 079285
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO REPAIR CASING	X	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Intex-South Penn Duro USL

May 3, 1960

Well No. #1-27 is located 660 ft. from N line and 1980 ft. from Ex line of sec. 27

NE/4 of NW/4 26 N., R. 1 E. N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)


Puerto Chiquita Rio Arriba New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 7301 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Run logs at T.D. 2663'. Plug back with sand stone to 2591' plus 1 sk Calseal to 2587'. Prep to run and cement 3 1/2" casing in dry hole at 2587' and test by hydrofracturing oil show from fractured shale at 2600' - 2663'.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company INTEX OIL COMPANY

Address P.O. Box 1411

Bakersfield, Calif.

PA 4-4956

By E. B. Miller
Title Production Manager