



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 079285
Unit _____

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	X
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	X
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Inter-South Perm

June 30, 1960

Well No. Duro 1-27 is located 660 ft. from N line and 1960 ft. from 1E line of sec. 27

NE/4 of NW/4
(1/4 Sec. and Sec. No.)

26 N.
(Twp.)

1 E.
(Range)

N.M.P.M.
(Meridian)

Puerto Chiquita
(Field)

Rio Arriba
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 7301 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Cleaned out and deepened with cable tools to 2745' in shale.
Lost bailer at 2745'. Lost spear on top of bailer.
Top of fish 2700'. (Not recovered).
Run 2-3/8" tubing with 5/8" rod and 1-1/2" pump.
Prep. to re-potential after cleaning out fractured zone 2586-2660'.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company INTEX OIL COMPANY

Address P. O. Box 1411

Bakersfield, California

By H. B. Miller
Title Production Manager